



## Release Note

**Edgecore EWS101 Release v3.91.0005**

**Document #** Edgecore\_EWS101\_ERN\_v3.91.0005

Enhancement from v3.90.0004

---

### Copyright Notification

### Edgecore Networks Corporation

© Copyright 2023 Edgecore Networks Corporation.

The information contained herein is subject to change without notice. This document is for informational purposes only and does not set forth any warranty, expressed or implied, concerning any equipment, equipment feature, or service offered by Edgecore Networks Corporation. Edgecore Networks Corporation shall not be liable for technical or editorial errors or omissions contained herein.

## Revision History

Date	Version	Author	Remark
2023/ 11 / 20	V1.0	Vincent Cheng	Release Note for v3.91.0005

## Table of Contents

1	AP Management Compatibility.....	3
1.1	Compatible Versions for AP Management.....	3
2	Feature Enhancement.....	4
2.1	Support EAP101 Hotspot 2.0 push config by template .....	4
2.2	Support ECW5211-L Hotspot 2.0 push config by template .....	4
2.3	Support band steering config on template .....	4
2.4	CAPWAP tunnels can be setup under IPv6 .....	4
2.5	Support Port Location Mapping for IPv6 complete tunnel.....	4
3	Issue Fixed.....	5
3.1	2.4G clients show wrong channel number in AP List > AP Online Users list when 2.4G and 5G use same SSID. ....	5
3.2	WiFi Monitor can't display the result of Signal Strength and Coverage .....	5
3.3	Create Floor plan in WiFi Monitor could freeze controller UI .....	5
3.4	Change EAP101 Tunnel config from N/A to grayed out "Edit" button in AP List page. ....	5
3.5	Time synchronization fails when EAP101's NTP server reference is set to EWS101. ....	5

# 1 AP Management Compatibility

## 1.1 Compatible Versions for AP Management

AP type	LAPM	WAPM	Compatible version
OAP100	V	V	3.45.0000 or newer
OAP100e	V	V	3.45.0000 or newer
EAP100	V	V	3.45.0000 or newer
ECW100	V	V	3.45.0000 or newer
ECW5210-L	V	V	3.45.0000 or newer
ECW5211-L	V	V	3.45.0000 or newer
ECW5410-L	V	V	3.45.0000 or newer
ECWO5210-L	V	V	3.45.0000 or newer
ECWO5211-L	V	V	3.45.0000 or newer
ECWO5213-L	V	V	3.45.0000 or newer
OAP103-BR		V	11.6.4 or newer
EAP101		V	11.2.0-795 or newer
EAP102		V	11.2.0-796 or newer
EAP104		V	12.0.0 or newer
SP-W2M-AC1200		V	7.0.0-2987 or newer
3rd Party		V	

## **2 Feature Enhancement**

### **2.1 Support EAP101 Hotspot 2.0 push config by template**

To support Hotspot 2.0 template for EAP101 v12.4.3(include) newer version in Template > New Generation > Hotspot 2.0 Settings

### **2.2 Support ECW5211-L Hotspot 2.0 push config by template**

To support Hotspot 2.0 template for ECW5211-L v3.45.00013(include) newer version in Template > Legacy > Hotspot 2.0 Settings

### **2.3 Support band steering config on template**

Support Band Steering for Legacy Template in General Settings > Band Steering Enable/Disable

### **2.4 CAPWAP tunnels can be setup under IPv6**

To support CAPWAP tunnels create by IPv6, all managed AP must use same IPv6 or IPv4 protocol, not support some AP managed by IPv6, some AP managed by IPv4.

### **2.5 Support Port Location Mapping for IPv6 complete tunnel.**

Support complete tunnel routing to LAN port with VLAN tag by PLM in Main > System > Port Location Mapping

### **3 Issue Fixed**

- 3.1 2.4G clients show wrong channel number in AP List > AP Online Users list when 2.4G and 5G use same SSID.**
- 3.2 WiFi Monitor can't display the result of Signal Strength and Coverage**
- 3.3 Create Floor plan in WiFi Monitor could freeze controller UI**
- 3.4 Change EAP101 Tunnel config from N/A to grayed out "Edit" button in AP List page.**
- 3.5 Time synchronization fails when EAP101's NTP server reference is set to EWS101.**